

UNSURPASSED QUALITY UNRIVATED SERVICE UNMATCHED REPUTATION

ARATRON II ELECTRONICS

ESD PRODUCTS—COMPONENT DISTRIBUTION

FIELD KIT-PORTABLE WORK AREA & MONITOR


INSTALLATION INSTRUCTIONS

- A) Unfold-Red Mat & lay on your work area
- B) Use ground cable on the left side. Snap snake head 3/8 mm, snap to mat and the other end must be grounded to utility ground

C) Right side use ground cable from 9211B monitor and snap to 3/8 snap (right side).

D) Plug wrist strap into monitor 9211B.

E) AEI 9211B is a battery operated ESD Monitor. Off and on switch will turn it on you will see red led blinking. Connect -wrist strap to black connector. <u>Your work area is know</u> <u>ESD SAFE</u>



Member of the ESD Association

21981 ANNETTE AVE, LAKE FOREST, CALIFORNIA 92630

PHONE: (949) 837-9138 FAX: (949) 837-6220

PROPERTIES

<u>Material</u>: Vinyl dissipative <u>Pocket</u>: Two

Thickness: 0.18mil

Colors: Red

Charge dicay: .01sec

<u>Size</u>: 24'' * 24''

AND

<u>Meets Standars</u>: S20.20, Mil-STD-1686 & HDBK-263

Wrist Strap: One Adjustable Band

SPECIFICATIONS

<u>Strap</u>: 8' & 10' light weight coil & ground

Strap: One 3/8' msnap

WWW.ARATRON.COM - ARAGONARATRON@AOL.COM PH. 949.837.9138 FX. 949.837.6220